



**WE ARE PROUD TO ANNOUNCE THAT  
ENECON HAS EXPANDED AND  
MOVED TO OUR NEW FACILITIES:  
150 Schmitt Blvd.,  
Farmingdale, NY 11735**

Enecon North East News  
Dec. 2017 | Vol 9, Issue 14

*ENECRETE & FLEXICLAD Protect  
New Clarifier At Canadian Iron Mill*



ENECRETE  
DURAQUARTZ



FLEXICLAD PC



ENESEAL CR



Vol 9 Issue 13  
Pump Bases Rebuild  
With ENECON  
Polymers



Vol 9 Issue 12  
University Water Leaks  
Solved With ENECON  
Polymers

Clarifier tanks, like this one, are used in the process to manufacture iron pellets. Pellets are small balls of iron ore used in the production of steel. These tanks help separate the tailings from the iron ore before the pellet manufacturing process begins.

After years of use and exposure to the elements, this tank at a pellet manufacturing plant in Canada needed to be replaced. The old tank was removed and ENECRETE DuraQuartz was used to repair the concrete base before the new tank was installed. Because this tank was situated between two buildings a 250 ton crane was used to lower the new tank sections into place.

DuraQuartz was used again to fill in any gaps where the tank met the uneven, old concrete base. The new tank and base were then joined and held in place using a bolted steel flange. The joint between the flange and the concrete base inside and outside of the tank were then sealed with FLEXICLAD PC. This will allow for expansion and contraction where these two dissimilar materials meet.

Lastly, ENESEAL CR was finally applied to the outer flange area to provide corrosion resistance.



DuraQuartz application



Then FLEXICLAD PC



Final application of ENESEAL CR



**CONTACT US TODAY TO LEARN MORE ABOUT OUR  
UNIQUE PRODUCTS AND SPECIALIZED PROJECT SERVICES**

ENECON Northeast A.P.S., Inc.  
150 Schmitt Blvd.  
Farmingdale, NY 11735  
Telephone: 631-414-7818  
Fax 631-414-7822  
Email: [solutions@eneconaps.com](mailto:solutions@eneconaps.com)  
Website: [www.eneconaps.com](http://www.eneconaps.com)



We Solve Your Toughest Fluid Flow Repair and Maintenance Problems

© Copyright 2017 ENECON® Northeast