



Enecon North East News
 July 2013 | Vol 5. Issue 8



Flexiclad ER



Volume 5 Issue 7: Food Manufacturer Coats HVAC Chiller



Volume 5 Issue 6: Above Ground Bulk Storage Tank Inspection & Repair

Check Out Our New Products

Universal Hinge
www.universalhinge.com



Leak Repair Kit

2 x 167 gm A-Packs SpeedAlloy

1 x 250 gm unit SpeedAlloy QS

Plus mixing board, mixing knife, plastic applicator, reinforcement tape, sandpaper roll, alcohol wipes and disposable gloves...

All packed in a handy tool box!




Pennsylvania Hospital Stops Leaking Dishwashing Tray Seams in their Kitchen with FLEXICLAD ER

ENECON has solved many 'standard' problems at this Pennsylvania hospital - repairs to cooling towers, chillers, floors, pipes, etc.

The hospital's maintenance engineers contacted the local ENECON Fluid Flow Systems Specialist with what they considered an 'unusual' problem. The seams of their stainless steel dishwashing tray line were leaking. This was causing slip/fall accidents, constant clean-up and generally unsanitary conditions. They had tried to fix the leaks numerous times with caulks, but with no success. It was quickly agreed that FLEXICALD ER would be used to solve this problem. The area's were manually prepared with sandpaper, then cleaned throughly. FLEXICLAD ER was applied, with no primer needed. The area was ready to be put back into action the next morning with no odor and no downtime.

The hospital maintenance staff was pleased with the results and ENECON continues to be the hospital's 'problem solver'.



Enecon announces new Emergency Leak Repair Kit. See our "new products" on the left side of the Newsletter.

CONTACT US TODAY TO LEARN MORE ABOUT OUR UNIQUE PRODUCTS AND SPECIALIZED PROJECT SERVICES

58 Florida Street, Farmingdale, NY 11735
 Telephone: 631-414-7818
 Fax 631-414-7822
 Email: solutions@eneconaps.com
 Website: www.eneconaps.com



We Solve Your Toughest Fluid Flow Repair and Maintenance Problems

© Copyright 2013 ENECON® Northeast