



Enecon North East News
Nov 2013 | Vol 5, Issue 12



Enecon EneSeal CR



Enecon DuraFill



Volume 5 Issue 11:
Pharmaceutical Rooftop
Air Handler Sealed



Volume 5 Issue 10:
EneSeal CR Protects &
Seals Corrugated Steel
Roof

Check Out Our New
Products

Universal Hinge
www.universalhinge.com



Leak Repair Kit

2 x 167 gm A-Packs
SpeedAlloy

1 x 250 gm unit
SpeedAlloy QS

Plus mixing board,
mixing knife, plastic
applicator, reinforcement
tape, sandpaper roll,
alcohol wipes and
disposable gloves...

All packed in a handy
tool box!



**ENECRETE & ENESEAL Repair Fire Damaged
Concrete Bases of 37 Ton Transformers**

Client: Northeastern U.S. Municipality

Problem: 2 Power transformers were involved in an accidental fire causing them both to have to be removed and eventually replaced. The onsite engineers were concerned about the integrity of the concrete bases the 37 ton transformers were mounted on. Cracks and damage were visible after the transformers were removed.

Solution: Loose concrete was removed from the bases as the area was manually prepared. Wood forms were built around the bases and **ENECRETE DuraFill**, mixed with a locally sourced aggregate, was used to repair all the damaged areas. **ENESEAL CR** was then applied to give the bases a uniform look as well as protect them from future environmental exposure. The engineers were pleased with ENECON's ability to provide a cost effective solution for this very serious problem.



Enecon announces new Emergency Leak Repair Kit. See our "new products" on the *left side* of the Newsletter.

**CONTACT US TODAY TO LEARN MORE ABOUT OUR
UNIQUE PRODUCTS AND SPECIALIZED PROJECT SERVICES**

58 Florida Street, Farmingdale, NY 11735
Telephone: 631-414-7818
Fax 631-414-7822
Email: solutions@eneconaps.com
Website: www.eneconaps.com