



Enecon North East News
 Oct 2014 | Vol 6. Issue 9



DuraQuartz



Enecrete WS



Enecrete DuraFill



Enecrete WP



Volume 6 Issue 8:
 Cooling Tower Corrosion Solution



Volume 6 Issue 7:
 Cavitation damage on Francis Turbine solved with Enecon

Check Out Our New Products

Universal Hinge
www.universalhinge.com



Leak Repair Kit

2 x 167 gm A-Packs SpeedAlloy

1 x 250 gm unit SpeedAlloy QS

Plus mixing board, mixing knife, plastic applicator, reinforcement tape, sandpaper roll, alcohol wipes and disposable gloves...

All packed in a handy tool box!



How to Solve Concrete Cracking & Deterioration Problems at Industrial & Commercial Facilities with ENECRETE



Concrete crack problems are so common at industrial and commercial facilities that virtually all buildings will experience deterioration at some point in time. This is due to shifting as structures move, de-icing salts, cleaners, and industrial chemicals. All of these can deteriorate concrete at an accelerated pace.



Electrical tower concrete base was crumbling due to exposure to the elements... ENECRETE DuraFill & DuraQuartz were used to rebuild the tower bases.



A subway tunnel developed serious leak problems due to hydrostatic pressure. Large cracks were letting in a significant amount of water. ENECRETE WP was used to repair the cracks and stop the water leaks. ENECRETE WS, a protective and waterproofing product for masonry structures, was then used to seal the walls against dampness and seepage.

Enecon announces new Emergency Leak Repair Kit. See our "new products" on the left side of the Newsletter.

CONTACT US TODAY TO LEARN MORE ABOUT OUR UNIQUE PRODUCTS AND SPECIALIZED PROJECT SERVICES

58 Florida Street, Farmingdale, NY 11735
 Telephone: 631-414-7818
 Fax 631-414-7822
 Email: solutions@eneconaps.com
 Website: www.eneconaps.com



We Solve Your Toughest Fluid Flow Repair and Maintenance Problems