



Enecon North East News
 Mar. 2016 | Vol 8. Issue 2



CHEMCLAD XC



ENECRETE DURAFILL



Vol 8 Issue 1
A Utility 30" Salt Water Line Repaired Using Carbon Fiber



Vol 7 Issue 11
"Tis the Season" for Chiller Maintenance

Enecon Corporation Announces New High Temperature Coatings
 Click to learn more about **CeramAlloy HTP** and **CeramAlloy HTL**



CeramAlloy HTP



CeramAlloy HTL

Deteriorating Containment Areas, Pump Bases, and Sumps in Need of Repair at Chemical Company




Problem:

When previous coatings had failed numerous times, a prestigious U.S. chemical company called on ENECON to protect its badly deteriorating containment areas, pump bases and sumps.



Solution:

ENECON provided a full turnkey solution. The surface was first prepared by removing all of the old and delaminating coating in all containment areas, pump bases and sumps. All surfaces were later primed with **ENECRETE DuraFill** followed by two top coats of **CHEMCLAD XC** for unrivaled chemical attack protection.



Result:

ENECON prides itself on these types of difficult industrial solutions because we not only have the right products, but we also have the know-how and expertise regarding surface prep, cure times in between coats, and all of the small details that go into a project like this for it to be not only effective, but also properly done the first time. This turnkey project was completed in less than two weeks with no plant down time. In addition to helping the customer comply with the local chemical containment area codes, this application will provide unsurpassed chemical attack protection for decades to come.

CONTACT US TODAY TO LEARN MORE ABOUT OUR UNIQUE PRODUCTS AND SPECIALIZED PROJECT SERVICES

58 Florida Street
 Farmingdale, NY 11735
 Telephone: 631-414-7818
 Fax 631-414-7822
 Email: solutions@eneconaps.com
 Website: www.eneconaps.com