



Enecon North East News
June 2016 | Vol 8. Issue 5

Deteriorating Containment Areas, Pump Bases & Sumps Repaired at Chemical Company

When previous coatings had failed numerous times, a chemical company called on ENECON to protect its badly deteriorating containment areas, pump bases and sumps.

The surfaces were first prepared by removing the old and delaminated coatings. All surfaces were later primed with ENECRETE DuraFill followed by two top coats of CHEMCLAD XC for unrivaled chemical attack protection.


This turnkey project was completed in less than two weeks with no plant downtime. In addition to helping the customer comply with chemical containment area codes, this application will provide unsurpassed chemical attack protection for many years to come.




CHEMCLAD XC



ENECRETE DURAFILL




Vol 8 Issue 4
Municipal Water Tank Coated



Vol 8 Issue 3
Cooling Tower Supply Line Repaired



Before



After



After



After



Before



After



After

CONTACT US TODAY TO LEARN MORE ABOUT OUR UNIQUE PRODUCTS AND SPECIALIZED PROJECT SERVICES

58 Florida Street
Farmingdale, NY 11735
Telephone: 631-414-7818
Fax 631-414-7822
Email: solutions@eneconaps.com
Website: www.eneconaps.com

ENECON[®] NORTH EAST APPLIED POLYMER SYSTEMS

We Solve Your Toughest Fluid Flow Repair and Maintenance Problems

© Copyright 2016 ENECON® Northeast