




Enecon North East News
Sept. 2016 | Vol 8. Issue 7



CHEMCLAD SC



Vol 8 Issue 6
Staircase Repair at
Local High School



Vol 8 Issue 5
Pump Pedestals,
Chemical Sumps,
Protected with
ENECON Coatings

CHEMCLAD SC NSF Approved For Potable Water Applications Protects Drinking Water Clarifier At Chemical Plant In New Jersey

This clarifier at a water treatment plant in New Jersey (approximately 80 feet long x 17 feet wide x 15 feet deep) was in need of critical repairs.

The clarifier is about 30 years old, with severely eroded concrete with aggregate protruding up to ½ inch. There were also several cracks that leaked through to adjacent tanks and through exterior walls, degrading those areas as well.

The client wanted the leaks stopped and the concrete sealed to retard future degradation.

ENECON had completed various smaller projects at this plant to seal and protect other concrete containment areas and waste water clarifiers with great success.

This project took 4 weeks to complete, due to schedules onsite and weather problems, but the client was very pleased.

There are 5 more of these tanks and one will be completed every year for the next 5 years.

ENECON was awarded another tank repair and protection project as a result of this job.



CONTACT US TODAY TO LEARN MORE ABOUT OUR UNIQUE PRODUCTS AND SPECIALIZED PROJECT SERVICES

58 Florida Street
Farmingdale, NY 11735
Telephone: 631-414-7818
Fax 631-414-7822
Email: solutions@eneconaps.com
Website: www.eneconaps.com

ENECON[®] NORTH EAST **APPLIED POLYMER SYSTEMS**

We Solve Your Toughest Fluid Flow Repair and Maintenance Problems

© Copyright 2016 ENECON® Northeast