




Enecon North East News  
 Jan. 2017 | Vol 9, Issue 1



ENECRETE DURAQUARTZ



CHEMCLAD SC



Vol 8 Issue 11  
 Florida Canal Pump Station Use ENECON To Save Concrete Floor



Vol 8 Issue 10  
 Cooling Tower Steel Beams Coated with ENECON

## Chemical Company Repairs & Protects Concrete Storage Tank

A chemical processing company was storing waste chemical solutions in this large concrete tank. The aggressive nature of the chemicals was attacking the concrete and causing serious damage. The local environmental authority shut the tank down until it had acceptable chemical protection.

The plant had several commercial painting companies propose materials and procedures for repairing and coating the tank, but none were acceptable to the authorities. ENECON was then called to provide a solution.

The surface was prepared by first removing all dirt, debris and loose concrete. All damaged areas were then repaired with ENECRETE Durafill mixed with a local aggregate.

The repairs to the tank took a total of 8 days; and, when completed, two coats of CHEMCLAD SC were applied by roller to completely protect the tank.

Afterwards the environmental authority approved the CHEMCLAD system and the company was permitted to continue using the tank.

This job was approximately 5,000 sq. ft.



**CONTACT US TODAY TO LEARN MORE ABOUT OUR UNIQUE PRODUCTS AND SPECIALIZED PROJECT SERVICES**

58 Florida Street  
 Farmingdale, NY 11735  
 Telephone: 631-414-7818  
 Fax 631-414-7822  
 Email: [solutions@eneconaps.com](mailto:solutions@eneconaps.com)  
 Website: [www.eneconaps.com](http://www.eneconaps.com)



*We Solve Your Toughest Fluid Flow Repair and Maintenance Problems*

© Copyright 2017 ENECON® Northeast