



Enecon North East News
 Mar 2014 | Vol 6, Issue 4



Ene seal HR



Ene seal CR



Volume 6 Issue 3: Steel Mill Water Main Repaired Using Durawrap



Volume 6 Issue 2: Utility Reclaims Pump with CeramAlloy

Check Out Our New Products

Universal Hinge
www.universalhinge.com



Leak Repair Kit

2 x 167 gm A-Packs
 SpeedAlloy

1 x 250 gm unit
 SpeedAlloy QS

Plus mixing board, mixing knife, plastic applicator, reinforcement tape, sandpaper roll, alcohol wipes and disposable gloves...

All packed in a handy tool box!




Northeastern U.S. Power Company Protects Switchgear Cabinet Roofs with ENESEAL

Client: Northeastern U.S. Power Company.

Problem: Aging switchgear cabinet roofs (constructed of galvanized sheet metal) were leaking at the seams and porcelain bushing penetrations.

Solution: After first removing the failing metal straps and rubber gaskets/seam covers, the entire roof was manually abraded. New 'coatable' roofing seam tape was applied to the open seams. ENESEAL CR was then applied as a 'primer' followed by two coats of ENESEAL HR.



Enecon announces new Emergency Leak Repair Kit. See our "new products" on the left side of the Newsletter.

CONTACT US TODAY TO LEARN MORE ABOUT OUR UNIQUE PRODUCTS AND SPECIALIZED PROJECT SERVICES

58 Florida Street, Farmingdale, NY 11735
 Telephone: 631-414-7818
 Fax 631-414-7822
 Email: solutions@eneconaps.com
 Website: www.eneconaps.com



We Solve Your Toughest Fluid Flow Repair and Maintenance Problems