



**WE ARE PROUD TO ANNOUNCE THAT
ENECON HAS EXPANDED AND
MOVED TO OUR NEW FACILITIES:
150 Schmitt Blvd.,
Farmingdale, NY 11735**

Enecon North East News
Nov. 2017 | Vol 9. Issue 12



ENESEAL CR



VISCOTAQ EZ-WRAP



VISCOTAQ
VISCOSSEALANT



Vol 9 Issue 11
CerAmAlloy Used To
Repair & Protect 35
Year Old Chiller



Vol 9 Issue 10
Leaking sewer line
sealed

**University Building Leaks Stopped
With ENESEAL**



An area where these roof top air circulation pipes converge to enter a university building was vulnerable to leaks from rainwater. When this area leaked, water would drip down to laboratories below filled with expensive equipment.

The pipes are spiral wound stainless steel, so corrosion is not a problem, however rainwater was entering the pipes through the pipe-winding joints.

Earlier spot repairs circled in the before photos were not effective. The university maintenance team needed a better solution.



All the joints were sealed with Viscotaq sealing tape followed by two coats of ENESEAL CR.

The ENECON solution solved the leak problem and the university maintenance team is extremely happy. The local ENECON Engineering Specialist is now looking at other similar solutions on campus.



**CONTACT US TODAY TO LEARN MORE ABOUT OUR
UNIQUE PRODUCTS AND SPECIALIZED PROJECT SERVICES**

ENECON Northeast A.P.S., Inc.
150 Schmitt Blvd.
Farmingdale, NY 11735
Telephone: 631-414-7818
Fax 631-414-7822
Email: solutions@eneconaps.com
Website: www.eneconaps.com



We Solve Your Toughest Fluid Flow Repair and Maintenance Problems

© Copyright 2017 ENECON® Northeast