



Enecon North East News
 Oct. 2018 | Vol 10, Issue 9



CERAMALLOY CBX



Vol 10 Issue 8
 A Utility Salvages One Million Gallon Tank with Enecon Coatings



Vol 10 Issue 7
 School Solves Unsightly Wall Issues

After 4+ Years Of Service In An Alumina Refinery, CeramAlloy CBX Is Still In Excellent Condition




Client:
 Alumina Refinery

Problem:
 Calciner screws, subjected to extreme abrasion typically only last 12-18 months.

This screw (image 1) was protected with CeramAlloy CBX and put back into service for over 4 years. After 4+ years in service.



After brush blasting clean, the CeramAlloy CBX is shown to still be in excellent condition (image 2). After cleaning, the CBX is still in excellent condition.



CONTACT US TODAY TO LEARN MORE ABOUT OUR UNIQUE PRODUCTS AND SPECIALIZED PROJECT SERVICES

ENECON Northeast A.P.S., Inc.
 150 Schmitt Blvd.
 Farmingdale, NY 11735
 Telephone: 631-414-7818
 Fax 631-414-7822
 Email: solutions@eneconaps.com
 Website: www.eneconaps.com



© Copyright 2018 ENECON® Northeast